

Florida Department of Law Enforcement

Diagnostic Tests

Instrument Serial #: 80-000206

Location	Date	Time	Source
FDLE/ATP PROC	07/12/2006	15:57:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000220

Location	Date	Time	Source
FDLE	07/12/2006	17:52:27	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000223

Location	Date	Time	Source
FDLE/ATP MELBOURNE	06/02/2006	03:31:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FDLE/ATP MELBOURNE	06/30/2006	09:17:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FDLE/ATP MELBOURNE	06/30/2006	09:42:27	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FDLE/ATP MELBOURNE	06/30/2006	09:50:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000223

Location	Date	Time	Source
FDLE/ATP MELBOURNE	06/30/2006	09:50:54	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FDLE/ATP MELBOURNE	06/30/2006	22:39:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000224

Location	Date	Time	Source
FDLE/ATP JROC	09/28/2006	15:11:59	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000737

Location	Date	Time	Source
ALACHUA COUNTY SO	07/13/2006	14:54:28	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-000739

Location	Date	Time	Source
OKALOOSA COUNTY SO	08/22/2006	08:58:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
OKALOOSA COUNTY SO	08/22/2006	09:00:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
OKALOOSA COUNTY SO	08/22/2006	09:02:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OKALOOSA COUNTY SO	08/22/2006	09:13:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000739

Location	Date	Time	Source
OKALOOSA COUNTY SO	08/22/2006	09:13:39	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OKALOOSA COUNTY SO	09/28/2006	09:08:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000742

Location	Date	Time	Source
VALPARAISO PD	05/10/2006	18:29:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
VALPARAISO PD	05/10/2006	18:52:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
VALPARAISO PD	07/02/2006	23:45:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
VALPARAISO PD	07/02/2006	23:46:37	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000742

Location	Date	Time	Source
VALPARAISO PD	07/02/2006	23:46:37	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
VALPARAISO PD	07/03/2006	00:14:25	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
VALPARAISO PD	07/03/2006	06:33:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
VALPARAISO PD	07/27/2006	14:50:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
VALPARAISO PD	07/27/2006	23:12:52	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-000742

Location	Date	Time	Source
VALPARAISO PD	07/27/2006	23:12:52	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
VALPARAISO PD	08/24/2006	00:05:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
VALPARAISO PD	08/24/2006	00:14:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
VALPARASIO PD	11/01/2006	19:22:13	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-000742

Location	Date	Time	Source
VALPARASIO PD	11/01/2006	19:22:13	Local Diagnostic
		Test	Result
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000744

Location	Date	Time	Source
ESCAMBIA COUNTY SO	03/27/2006	15:06:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ESCAMBIA COUNTY SO	03/27/2006	15:08:15	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000752

Location	Date	Time	Source
MARION COUNTY SO	06/06/2006	15:59:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MARION COUNTY SO	06/06/2006	16:00:17	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000760

Location	Date	Time	Source
ALACHUA COUNTY SO	04/30/2006	15:46:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000763

Location	Date	Time	Source
OKALOOSA COUNTY SO	04/08/2006	14:49:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OKALOOSA COUNTY SO	06/30/2006	18:48:37	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
OKALOOSA COUNTY SO	06/30/2006	18:49:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000765

Location	Date	Time	Source
SANTA ROSA COUNTY SO	03/27/2006	03:11:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	06/30/2006	21:31:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	07/08/2006	03:16:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	09/07/2006	10:15:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000765

Location	Date	Time	Source
SANTA ROSA CO SO	09/07/2006	10:15:39	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	10/12/2006	23:33:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	10/24/2006	21:25:31	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	11/15/2006	22:29:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	12/07/2006	01:22:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-000765

Location	Date	Time	Source
SANTA ROSA CO SO	12/07/2006	01:22:49	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	12/24/2006	22:42:17	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000768

Location	Date	Time	Source
SUWANNEE COUNTY SO	09/30/2006	22:03:43	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000770

Location	Date	Time	Source
HAMILTON COUNTY S.O.	03/22/2006	09:34:11	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-000772

Location	Date	Time	Source
SANTA ROSA COUNTY SO	03/27/2006	02:14:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	05/30/2006	22:33:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	05/30/2006	22:34:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	06/25/2006	01:52:05	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000772

Location	Date	Time	Source
SANTA ROSA COUNTY SO	06/25/2006	01:52:05	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	07/08/2006	02:06:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	07/10/2006	02:24:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	09/07/2006	09:26:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	10/12/2006	22:43:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-000772

Location	Date	Time	Source
SANTA ROSA COUNTY SO	10/12/2006	22:43:39	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000775

Location	Date	Time	Source
COLUMBIA COUNTY SO	05/22/2006	06:32:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
COLUMBIA COUNTY SO	05/22/2006	06:34:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000777

Location	Date	Time	Source
COLUMBIA COUNTY SO	06/16/2006	11:41:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
COLUMBIA COUNTY SO	06/16/2006	11:42:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000780

Location	Date	Time	Source
SUWANNEE COUNTY SO	03/14/2006	15:08:10	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000784

Location	Date	Time	Source
HOLMES COUNTY SO	03/17/2006	09:18:32	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000785

Location	Date	Time	Source
HOLMES COUNTY SO	03/27/2006	09:23:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HOLMES COUNTY SO	03/27/2006	12:34:05	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
HOLMES COUNTY SO	03/27/2006	12:54:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000788

Location	Date	Time	Source
ST LUCIE COUNTY SO	03/22/2006	10:59:06	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000790

Location	Date	Time	Source
VERO BEACH PD	10/30/2006	19:12:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	Fail
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
VERO BEACH PD	10/30/2006	19:15:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	Fail
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
VERO BEACH PD	12/06/2006	09:01:45	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
VERO BEACH PD	12/12/2006	13:23:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000790

Location	Date	Time	Source
VERO BEACH PD	12/12/2006	13:23:47	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000792

Location	Date	Time	Source
ST LUCIE COUNTY SO	04/11/2006	09:15:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
ST LUCIE COUNTY SO	12/01/2006	23:37:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000795

Location	Date	Time	Source
GULF COUNTY SO	03/27/2006	14:50:34	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000796

Location	Date	Time	Source
LONGBOAT KEY PD	03/22/2006	15:46:27	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000808

Location	Date	Time	Source
HILLSBOROUGH SO	03/22/2006	12:16:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
HILLSBOROUGH SO	03/22/2006	12:18:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
HILLSBOROUGH SO	03/22/2006	12:35:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	03/27/2006	14:40:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000808

Location	Date	Time	Source
HILLSBOROUGH SO	03/27/2006	14:40:57	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000812

Location	Date	Time	Source
HERNANDO COUNTY SO	03/22/2006	13:45:06	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-000817

Location	Date	Time	Source
CITRUS COUNTY SO	03/22/2006	11:52:58	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CITRUS COUNTY SO	04/27/2006	16:53:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000819

Location	Date	Time	Source
CITRUS COUNTY SO	08/31/2006	08:04:55	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CITRUS COUNTY SO	10/25/2006	18:46:33	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000822

Location	Date	Time	Source
LAKE SO	08/08/2006	15:51:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LAKE SO	10/25/2006	07:01:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000823

Location	Date	Time	Source
LAKE S.O.	10/25/2006	07:02:29	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000824

Location	Date	Time	Source
LEESBURG PD	03/27/2006	12:23:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEESBURG PD	03/31/2006	15:10:45	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEESBURG PD	03/31/2006	15:17:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEESBURG PD	05/08/2006	16:28:05	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000824

Location	Date	Time	Source
LEESBURG PD	05/08/2006	16:28:05	Local Diagnostic
Test			Result
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-000829

Location	Date	Time	Source
HILLSBOROUGH SO	03/27/2006	14:15:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	10/20/2006	22:09:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	11/03/2006	22:25:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
HILLSBOROUGH SO	11/03/2006	22:42:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000829

Location	Date	Time	Source
HILLSBOROUGH SO	11/03/2006	22:42:30	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000830

Location	Date	Time	Source
HILLSBOROUGH SO	03/22/2006	10:24:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	03/22/2006	10:32:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	03/22/2006	10:34:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	03/27/2006	09:53:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000830

Location	Date	Time	Source
HILLSBOROUGH SO	03/27/2006	09:53:36	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	05/12/2006	23:21:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	05/13/2006	00:28:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	06/16/2006	22:09:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
HILLSBOROUGH SO	06/16/2006	22:11:25	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-000830

Location	Date	Time	Source
HILLSBOROUGH SO	06/16/2006	22:11:25	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
HILLSBOROUGH SO	06/16/2006	22:48:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	07/27/2006	22:24:28	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	08/12/2006	00:09:05	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-000830

Location	Date	Time	Source
HILLSBOROUGH SO	08/12/2006	00:09:05	Local Diagnostic
		Test	Result
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	10/20/2006	22:09:58	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	11/10/2006	20:56:25	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000832

Location	Date	Time	Source
MARTIN COUNTY SO	10/11/2006	08:47:28	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MARTIN COUNTY SO	10/11/2006	08:55:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MARTIN COUNTY SO	10/11/2006	09:02:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000833

Location	Date	Time	Source
HILLSBOROUGH SO	03/24/2006	12:30:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	04/03/2006	11:15:55	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	12/27/2006	10:37:37	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000838

Location	Date	Time	Source
PANAMA CITY BEACH PD	04/29/2006	10:39:05	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
PANAMA CITY BEACH PD	04/29/2006	10:40:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000840

Location	Date	Time	Source
LYNN HAVEN PD	08/04/2006	18:16:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LYNN HAVEN PD	10/09/2006	11:38:31	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LYNN HAVEN PD	10/09/2006	11:51:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000861

Location	Date	Time	Source
SARASOTA COUNTY SO	04/06/2006	08:10:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
SARASOTA COUNTY SO	04/19/2006	19:55:07	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000862

Location	Date	Time	Source
BLOUNTSTOWN PD	03/28/2006	12:16:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
BLOUNTSTOWN PD	03/28/2006	12:19:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
BLOUNTSTOWN PD	03/28/2006	12:22:07	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000869

Location	Date	Time	Source
MONROE COUNTY SO	01/10/2006	13:25:15	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000871

Location	Date	Time	Source
CORAL GABLES PD	03/09/2006	20:59:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CORAL GABLES PD	04/29/2006	00:13:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CORAL GABLES PD	07/29/2006	04:19:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000872

Location	Date	Time	Source
MIAMI PD	02/21/2006	19:27:23	Local Diagnostic
Test		Result	
Voltage/Current Test		OK	
RAM Test		OK	
EEPROM Checksum Test		OK	
Real Time Clock Test		OK	
DSP Test		OK	
Analytical Stability Test		OK	
Internal Printer Test		OK	
Modem Test		OK	
Temperature Regulation Test		OK	

Diagnostic Tests

Instrument Serial #: 80-000874

Location	Date	Time	Source
MIAMI PD	02/21/2006	19:27:43	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000875

Location	Date	Time	Source
CALHOUN COUNTY SO	03/26/2006	21:28:06	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CALHOUN COUNTY SO	06/27/2006	20:43:46	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CALHOUN COUNTY SO	07/30/2006	21:37:33	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	
CALHOUN COUNTY SO	08/12/2006	07:42:44	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000875

Location	Date	Time	Source
CALHOUN COUNTY SO	08/12/2006	07:42:44	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
CALHOUN COUNTY SO	08/12/2006	07:51:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
CALHOUN COUNTY SO	08/12/2006	08:33:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000876

Location	Date	Time	Source
HIALEAH PD	03/08/2006	21:54:15	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000878

Location	Date	Time	Source
HOMESTEAD PD	03/09/2006	17:12:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HOMESTEAD PD	03/21/2006	22:00:53	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HOMESTEAD PD	03/21/2006	22:01:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000879

Location	Date	Time	Source
MIAMI BEACH PD	03/09/2006	11:50:33	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI BEACH PD	04/09/2006	23:16:32	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI BEACH PD	04/10/2006	02:42:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI BEACH PD	05/11/2006	03:31:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000879

Location	Date	Time	Source
MIAMI BEACH PD	05/11/2006	03:31:51	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	05/11/2006	14:18:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI BEACH PD	07/29/2006	02:19:15	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI BEACH PD	08/13/2006	00:45:28	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	08/13/2006	00:46:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-000879

Location	Date	Time	Source
MIAMI BEACH PD	08/13/2006	00:46:18	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	08/13/2006	00:47:28	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI BEACH PD	09/25/2006	23:33:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000881

Location	Date	Time	Source
MIAMI-DADE PD	02/21/2006	15:32:30	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-000882

Location	Date	Time	Source
MIAMI-DADE PD	10/27/2006	17:58:22	Local Diagnostic
Test		Result	
Voltage/Current Test		OK	
RAM Test		OK	
EEPROM Checksum Test		OK	
Real Time Clock Test		OK	
DSP Test		OK	
Analytical Stability Test		OK	
Internal Printer Test		OK	
Modem Test		OK	
Temperature Regulation Test		OK	

Diagnostic Tests

Instrument Serial #: 80-000883

Location	Date	Time	Source
MIAMI-DADE PD	03/27/2006	01:49:08	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			Fail

Diagnostic Tests

Instrument Serial #: 80-000884

Location	Date	Time	Source
MIAMI-DADE PD	06/15/2006	01:56:41	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-000885

Location	Date	Time	Source
MIAMI-DADE PD	02/21/2006	15:32:26	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000887

Location	Date	Time	Source
CHATTAHOOCHEE PD	03/26/2006	22:15:56	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			Fail

Diagnostic Tests

Instrument Serial #: 80-000889

Location	Date	Time	Source
PINELLAS COUNTY SO	07/06/2006	21:53:30	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000890

Location	Date	Time	Source
PINELLAS COUNTY SO	03/23/2006	23:00:29	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
PINELLAS COUNTY SO	03/23/2006	23:03:10	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
PINELLAS COUNTY SO	10/23/2006	15:23:02	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	
PINELLAS COUNTY SO	10/23/2006	15:37:32	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000890

Location	Date	Time	Source
PINELLAS COUNTY SO	10/23/2006	15:37:32	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	10/23/2006	15:41:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000891

Location	Date	Time	Source
FFWCC (PANAMA CITY)	04/05/2006	09:23:07	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-000892

Location	Date	Time	Source
FFWCC (PANAMA CITY)	04/05/2006	09:21:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000900

Location	Date	Time	Source
FFWCC (LAKE CITY)	10/20/2006	12:44:11	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-000904

Location	Date	Time	Source
FISH & WILDLIFE CC	03/25/2006	14:05:14	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FISH & WILDLIFE CC	03/25/2006	14:06:14	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FISH & WILDLIFE CC	03/25/2006	14:10:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000906

Location	Date	Time	Source
FISH & WILDLIFE CC	05/12/2006	10:41:51	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-000907

Location	Date	Time	Source
MANATEE COUNTY SO	03/27/2006	12:10:52	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	03/27/2006	12:11:28	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	07/11/2006	13:47:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	08/11/2006	18:15:15	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000907

Location	Date	Time	Source
MANATEE COUNTY SO	08/11/2006	18:15:15	Local Diagnostic
Test		Result	
Internal Printer Test		OK	
Modem Test		OK	
Temperature Regulation Test		OK	

Diagnostic Tests

Instrument Serial #: 80-000908

Location	Date	Time	Source
PORT ST JOE PD	03/27/2006	14:50:58	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000909

Location	Date	Time	Source
PINECREST PD	03/09/2006	17:12:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINECREST PD	03/25/2006	21:40:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINECREST PD	08/18/2006	12:29:56	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINECREST PD	09/05/2006	17:09:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000909

Location	Date	Time	Source
PINECREST PD	09/05/2006	17:09:00	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000912

Location	Date	Time	Source
MANATEE COUNTY SO	03/27/2006	14:35:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MANATEE COUNTY SO	03/27/2006	15:33:52	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	04/07/2006	23:41:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	04/11/2006	18:45:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000912

Location	Date	Time	Source
MANATEE COUNTY SO	04/11/2006	18:45:01	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	07/03/2006	01:03:33	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	08/17/2006	05:30:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000913

Location	Date	Time	Source
MANATEE COUNTY SO	03/27/2006	16:08:08	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000937

Location	Date	Time	Source
SANIBEL PD	02/16/2006	16:07:17	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000941

Location	Date	Time	Source
COLLIER COUNTY SO	03/27/2006	02:52:52	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
COLLIER COUNTY SO	03/27/2006	02:53:45	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
COLLIER COUNTY SO	03/27/2006	02:58:53	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
COLLIER COUNTY SO	03/27/2006	03:05:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000941

Location	Date	Time	Source
COLLIER COUNTY SO	03/27/2006	03:05:59	Local Diagnostic
	Test		Result
	Internal Printer Test		OK
	Modem Test		OK
	Temperature Regulation Test		OK

Diagnostic Tests

Instrument Serial #: 80-000943

Location	Date	Time	Source
COLLIER COUNTY SO	03/01/2006	11:37:01	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000945

Location	Date	Time	Source
CHARLOTTE COUNTY SO	05/24/2006	21:39:04	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000946

Location	Date	Time	Source
CHARLOTTE COUNTY SO	11/18/2006	23:09:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CHARLOTTE COUNTY SO	11/18/2006	23:10:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000949

Location	Date	Time	Source
TALLAHASSEE PD	03/22/2006	14:03:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
TALLAHASSEE PD	05/31/2006	10:41:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TALLAHASSEE PD	05/31/2006	11:24:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TALLAHASSEE PD	06/01/2006	07:52:37	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000949

Location	Date	Time	Source
TALLAHASSEE PD	06/01/2006	07:52:37	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TALLAHASSEE PD	06/01/2006	08:44:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TALLAHASSEE PD	07/14/2006	12:42:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
TALLAHASSEE PD	07/26/2006	12:25:46	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TALLAHASSEE PD	08/24/2006	10:11:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-000949

Location	Date	Time	Source
TALLAHASSEE PD	08/24/2006	10:11:43	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TALLAHASSEE PD	11/11/2006	18:29:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TALLAHASSEE PD	11/11/2006	18:30:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000950

Location	Date	Time	Source
HAVANNA PD	02/02/2006	09:56:24	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000951

Location	Date	Time	Source
HENDRY COUNTY SO	03/07/2006	17:10:09	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000952

Location	Date	Time	Source
FRANKLIN COUNTY SO	12/18/2006	11:30:08	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	Fail
		Temperature Regulation Test	OK
FRANKLIN COUNTY SO	12/18/2006	11:48:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	Fail
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000955

Location	Date	Time	Source
CLEWISTON PD	03/07/2006	17:09:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLEWISTON PD	05/06/2006	12:10:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
CLEWISTON PD	05/06/2006	12:15:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000957

Location	Date	Time	Source
LEON COUNTY SO	07/13/2006	14:05:27	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LEON COUNTY SO	07/13/2006	14:21:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEON COUNTY SO	07/13/2006	14:33:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEON COUNTY SO	12/19/2006	10:09:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000957

Location	Date	Time	Source
LEON COUNTY SO	12/19/2006	10:09:57	Local Diagnostic
<hr/>			
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
<hr/>			

Diagnostic Tests

Instrument Serial #: 80-000958

Location	Date	Time	Source
LEON COUNTY SO	07/13/2006	13:59:52	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEON COUNTY SO	07/13/2006	14:02:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEON COUNTY SO	12/19/2006	10:09:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000960

Location	Date	Time	Source
LIBERTY COUNTY SO	07/19/2006	15:49:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LIBERTY COUNTY SO	11/02/2006	16:26:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000961

Location	Date	Time	Source
WAKULLA COUNTY SO	04/03/2006	10:06:45	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-000963

Location	Date	Time	Source
ORANGE COUNTY SO	07/11/2006	11:49:40	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000965

Location	Date	Time	Source
QUINCY PD	03/24/2006	11:58:58	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	Fail		

Diagnostic Tests

Instrument Serial #: 80-000966

Location	Date	Time	Source
OSCEOLA CORRECTIONS	03/23/2006	16:06:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OSCEOLA CORRECTIONS	03/29/2006	09:31:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000968

Location	Date	Time	Source
OSCEOLA CORRECTIONS	03/29/2006	09:33:17	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OSCEOLA CORRECTIONS	03/29/2006	09:34:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OSCEOLA CORRECTIONS	05/17/2006	11:54:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000995

Location	Date	Time	Source
COCOA BEACH PD	03/23/2006	14:20:36	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000998

Location	Date	Time	Source
SEMINOLE SO	03/31/2006	02:06:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SEMINOLE SO	05/06/2006	00:21:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SEMINOLE SO	05/26/2006	21:43:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000999

Location	Date	Time	Source
SEMINOLE SO	03/31/2006	00:58:43	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SEMINOLE SO	07/28/2006	23:28:07	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SEMINOLE S.O.	11/15/2006	23:43:59	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001000

Location	Date	Time	Source
COCOA PD	01/17/2006	14:12:51	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001001

Location	Date	Time	Source
SATELLITE BEACH PD	09/10/2006	10:15:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
SATELLITE BEACH PD	09/10/2006	10:36:46	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SATELLITE BEACH PD	09/10/2006	10:40:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001002

Location	Date	Time	Source
HARDEE COUNTY SO	09/22/2006	16:12:57	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001003

Location	Date	Time	Source
PINELLAS COUNTY SO	06/14/2006	11:25:15	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001005

Location	Date	Time	Source
PINELLAS COUNTY SO	07/29/2006	22:42:32	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	07/29/2006	22:48:45	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001006

Location	Date	Time	Source
INDIALANTIC PD	03/21/2006	09:28:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
INDIALANTIC PD	03/21/2006	10:07:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
INDIALANTIC PD	10/27/2006	11:31:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001008

Location	Date	Time	Source
WEST MELBOURNE PD	04/21/2006	01:37:58	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
WEST MELBOURNE PD	04/21/2006	01:38:35	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001009

Location	Date	Time	Source
PALM BAY PD	02/14/2006	09:59:56	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001043

Location	Date	Time	Source
HIGHLANDS COUNTY SO	03/16/2006	16:28:04	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001051

Location	Date	Time	Source
ST PETERSBURG PD	03/10/2006	00:46:24	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001052

Location	Date	Time	Source
JACKSONVILLE SO	10/16/2006	13:21:21	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001054

Location	Date	Time	Source
HIGHLANDS COUNTY SO	11/15/2006	15:32:05	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001056

Location	Date	Time	Source
DAVIE PD	04/24/2006	18:04:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001057

Location	Date	Time	Source
LAKELAND PD	08/03/2006	14:15:08	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001059

Location	Date	Time	Source
FERNANDINA BEACH PD	03/27/2006	13:14:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001060

Location	Date	Time	Source
WINTER HAVEN PD	05/17/2006	15:00:17	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
WINTER HAVEN PD	05/30/2006	12:56:07	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001061

Location	Date	Time	Source
GULFPORT PD	03/27/2006	15:33:16	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001062

Location	Date	Time	Source
TREASURE ISLAND PD	03/28/2006	12:53:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TREASURE ISLAND PD	04/27/2006	12:29:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TREASURE ISLAND PD	09/18/2006	07:07:26	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
TREASURE ISLAND PD	09/18/2006	10:40:33	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001062

Location	Date	Time	Source
TREASURE ISLAND PD	09/18/2006	10:40:33	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-001063

Location	Date	Time	Source
HOLLYWOOD PD	03/23/2006	21:33:15	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001064

Location	Date	Time	Source
NEW PORT RICHEY PD	03/15/2006	18:24:58	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
NEW PORT RICHEY PD	03/16/2006	18:45:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
NEW PORT RICHEY PD	12/11/2006	16:09:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001068

Location	Date	Time	Source
CLEARWATER PD	05/03/2006	11:57:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLEARWATER PD	10/20/2006	04:42:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001070

Location	Date	Time	Source
FT MEADE PD	02/21/2006	09:09:30	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001071

Location	Date	Time	Source
CLAY COUNTY SO	04/13/2006	20:53:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLAY COUNTY SO	05/06/2006	03:57:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLAY COUNTY SO	05/06/2006	09:53:37	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001076

Location	Date	Time	Source
ZEPHYRHILLS PD	07/31/2006	16:50:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
ZEPHYRHILLS PD	12/19/2006	11:33:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001080

Location	Date	Time	Source
POLK COUNTY SO	03/17/2006	08:26:48	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001081

Location	Date	Time	Source
PASCO COUNTY SO	06/06/2006	14:35:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PASCO COUNTY SO	12/14/2006	15:57:31	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	Fail
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PASCO COUNTY SO	12/14/2006	15:59:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	Fail
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001082

Location	Date	Time	Source
PLANTATION PD	03/25/2006	21:57:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001083

Location	Date	Time	Source
JACKSONVILLE SO	09/20/2006	06:13:51	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001109

Location	Date	Time	Source
FHP TP C PINELLAS PK	06/20/2006	15:50:58	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001110

Location	Date	Time	Source
FHP TROOP E MIAMI	09/07/2006	09:47:52	Remote Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001112

Location	Date	Time	Source
FL HIGHWAY PATROL	03/24/2006	09:08:14	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FL HIGHWAY PATROL	03/24/2006	10:24:35	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001113

Location	Date	Time	Source
FHP TROOP C TAMPA	06/20/2006	15:50:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP C TAMPA	06/28/2006	11:14:56	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FHP TROOP C TAMPA	06/28/2006	11:16:33	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FHP TROOP C TAMPA	06/28/2006	11:19:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001113

Location	Date	Time	Source
FHP TROOP C TAMPA	06/28/2006	11:19:40	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FHP TROOP C TAMPA	06/28/2006	11:23:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP C TAMPA	06/28/2006	11:33:46	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FHP TROOP C TAMPA	06/28/2006	11:40:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP C TAMPA	06/30/2006	21:06:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001113

Location	Date	Time	Source
FHP TROOP C TAMPA	06/30/2006	21:06:36	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FHP TROOP C TAMPA	06/30/2006	21:07:27	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP C TAMPA	07/08/2006	22:04:27	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FHP TROOP C TAMPA	08/27/2006	19:22:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-001113

Location	Date	Time	Source
FHP TROOP C TAMPA	08/27/2006	19:22:10	Local Diagnostic
	Test	Result	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001116

Location	Date	Time	Source
EGLIN AFB	08/06/2006	03:58:10	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001118

Location	Date	Time	Source
FHP TROOP C LOL	02/15/2006	16:25:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FHP TROOP C LOL	04/01/2006	17:16:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001119

Location	Date	Time	Source
FHP TROOP D - DELAND	05/04/2006	16:45:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP D - DELAND	05/04/2006	19:46:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP D - DELAND	06/06/2006	09:25:07	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP D - DELAND	06/06/2006	11:27:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001119

Location	Date	Time	Source
FHP TROOP D - DELAND	06/06/2006	11:27:57	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP D - DELAND	08/16/2006	09:27:14	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP D - DELAND	08/16/2006	09:28:45	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001123

Location	Date	Time	Source
FHP TROOP F FT MYERS	03/20/2006	15:06:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP F FT MYERS	04/27/2006	09:48:35	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001128

Location	Date	Time	Source
PUTNAM COUNTY SO	03/29/2006	19:11:24	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-001129

Location	Date	Time	Source
PUTNAM COUNTY SO	03/27/2006	15:34:14	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PUTNAM COUNTY SO	08/03/2006	19:25:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
PUTNAM COUNTY SO	08/03/2006	19:27:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
PUTNAM COUNTY SO	08/03/2006	19:35:46	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001129

Location	Date	Time	Source
PUTNAM COUNTY SO	08/03/2006	19:35:46	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001130

Location	Date	Time	Source
VOLUSIA S0	05/30/2006	17:02:47	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001131

Location	Date	Time	Source
VOLUSIA SO	02/24/2006	10:40:17	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001133

Location	Date	Time	Source
ST JOHN'S COUNTY SO	03/27/2006	08:27:31	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST JOHN'S COUNTY SO	03/27/2006	08:28:37	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST JOHN'S COUNTY SO	03/27/2006	08:46:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST JOHN'S COUNTY SO	04/30/2006	09:27:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001133

Location	Date	Time	Source
ST JOHN'S COUNTY SO	04/30/2006	09:27:29	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST JOHN'S COUNTY SO	05/25/2006	11:24:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
ST JOHN'S COUNTY SO	05/25/2006	11:25:28	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
ST JOHN'S COUNTY SO	06/13/2006	15:13:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
ST JOHN'S COUNTY SO	06/29/2006	15:54:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001133

Location	Date	Time	Source
ST JOHN'S COUNTY SO	06/29/2006	15:54:42	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
ST JOHN'S COUNTY SO	09/12/2006	22:51:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001134

Location	Date	Time	Source
ST JOHN'S COUNTY SO	03/27/2006	06:40:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST JOHN'S COUNTY SO	03/27/2006	06:49:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST JOHN'S COUNTY SO	03/27/2006	08:09:46	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST JOHN'S COUNTY SO	05/25/2006	11:02:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001134

Location	Date	Time	Source																				
ST JOHN'S COUNTY SO	05/25/2006	11:02:36	Local Diagnostic																				
		<table border="1" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Test</th> <th style="text-align: left;">Result</th> </tr> </thead> <tbody> <tr> <td>Internal Printer Test</td> <td>OK</td> </tr> <tr> <td>Modem Test</td> <td>OK</td> </tr> <tr> <td>Temperature Regulation Test</td> <td>OK</td> </tr> </tbody> </table>	Test	Result	Internal Printer Test	OK	Modem Test	OK	Temperature Regulation Test	OK													
Test	Result																						
Internal Printer Test	OK																						
Modem Test	OK																						
Temperature Regulation Test	OK																						
ST JOHN'S COUNTY SO	06/02/2006	23:01:03	Local Diagnostic																				
		<table border="1" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Test</th> <th style="text-align: left;">Result</th> </tr> </thead> <tbody> <tr> <td>Voltage/Current Test</td> <td>OK</td> </tr> <tr> <td>RAM Test</td> <td>OK</td> </tr> <tr> <td>EEPROM Checksum Test</td> <td>OK</td> </tr> <tr> <td>Real Time Clock Test</td> <td>OK</td> </tr> <tr> <td>DSP Test</td> <td>OK</td> </tr> <tr> <td>Analytical Stability Test</td> <td>OK</td> </tr> <tr> <td>Internal Printer Test</td> <td>OK</td> </tr> <tr> <td>Modem Test</td> <td>OK</td> </tr> <tr> <td>Temperature Regulation Test</td> <td>OK</td> </tr> </tbody> </table>	Test	Result	Voltage/Current Test	OK	RAM Test	OK	EEPROM Checksum Test	OK	Real Time Clock Test	OK	DSP Test	OK	Analytical Stability Test	OK	Internal Printer Test	OK	Modem Test	OK	Temperature Regulation Test	OK	
Test	Result																						
Voltage/Current Test	OK																						
RAM Test	OK																						
EEPROM Checksum Test	OK																						
Real Time Clock Test	OK																						
DSP Test	OK																						
Analytical Stability Test	OK																						
Internal Printer Test	OK																						
Modem Test	OK																						
Temperature Regulation Test	OK																						
ST JOHN'S COUNTY SO	06/02/2006	23:01:51	Local Diagnostic																				
		<table border="1" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Test</th> <th style="text-align: left;">Result</th> </tr> </thead> <tbody> <tr> <td>Voltage/Current Test</td> <td>OK</td> </tr> <tr> <td>RAM Test</td> <td>OK</td> </tr> <tr> <td>EEPROM Checksum Test</td> <td>OK</td> </tr> <tr> <td>Real Time Clock Test</td> <td>OK</td> </tr> <tr> <td>DSP Test</td> <td>OK</td> </tr> <tr> <td>Analytical Stability Test</td> <td>OK</td> </tr> <tr> <td>Internal Printer Test</td> <td>OK</td> </tr> <tr> <td>Modem Test</td> <td>OK</td> </tr> <tr> <td>Temperature Regulation Test</td> <td>OK</td> </tr> </tbody> </table>	Test	Result	Voltage/Current Test	OK	RAM Test	OK	EEPROM Checksum Test	OK	Real Time Clock Test	OK	DSP Test	OK	Analytical Stability Test	OK	Internal Printer Test	OK	Modem Test	OK	Temperature Regulation Test	OK	
Test	Result																						
Voltage/Current Test	OK																						
RAM Test	OK																						
EEPROM Checksum Test	OK																						
Real Time Clock Test	OK																						
DSP Test	OK																						
Analytical Stability Test	OK																						
Internal Printer Test	OK																						
Modem Test	OK																						
Temperature Regulation Test	OK																						
ST JOHN'S COUNTY SO	06/02/2006	23:03:20	Local Diagnostic																				
		<table border="1" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Test</th> <th style="text-align: left;">Result</th> </tr> </thead> <tbody> <tr> <td>Voltage/Current Test</td> <td>OK</td> </tr> <tr> <td>RAM Test</td> <td>OK</td> </tr> <tr> <td>EEPROM Checksum Test</td> <td>OK</td> </tr> <tr> <td>Real Time Clock Test</td> <td>OK</td> </tr> <tr> <td>DSP Test</td> <td>OK</td> </tr> <tr> <td>Analytical Stability Test</td> <td>OK</td> </tr> <tr> <td>Internal Printer Test</td> <td>OK</td> </tr> <tr> <td>Modem Test</td> <td>OK</td> </tr> <tr> <td>Temperature Regulation Test</td> <td>OK</td> </tr> </tbody> </table>	Test	Result	Voltage/Current Test	OK	RAM Test	OK	EEPROM Checksum Test	OK	Real Time Clock Test	OK	DSP Test	OK	Analytical Stability Test	OK	Internal Printer Test	OK	Modem Test	OK	Temperature Regulation Test	OK	
Test	Result																						
Voltage/Current Test	OK																						
RAM Test	OK																						
EEPROM Checksum Test	OK																						
Real Time Clock Test	OK																						
DSP Test	OK																						
Analytical Stability Test	OK																						
Internal Printer Test	OK																						
Modem Test	OK																						
Temperature Regulation Test	OK																						
ST JOHN'S COUNTY SO	06/02/2006	23:05:00	Local Diagnostic																				
		<table border="1" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Test</th> <th style="text-align: left;">Result</th> </tr> </thead> <tbody> <tr> <td>Voltage/Current Test</td> <td>Fail</td> </tr> </tbody> </table>	Test	Result	Voltage/Current Test	Fail																	
Test	Result																						
Voltage/Current Test	Fail																						

Diagnostic Tests

Instrument Serial #: 80-001134

Location	Date	Time	Source
ST JOHN'S COUNTY SO	06/02/2006	23:05:00	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST JOHN'S COUNTY SO	06/02/2006	23:06:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	Fail
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST JOHN'S COUNTY SO	06/02/2006	23:12:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST JOHN'S COUNTY SO	06/13/2006	15:14:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-001134

Location	Date	Time	Source
ST JOHN'S COUNTY SO	06/13/2006	15:14:23	Local Diagnostic
		Test	Result
		Modem Test	OK
		Temperature Regulation Test	Fail
ST JOHN'S COUNTY SO	06/29/2006	15:54:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
ST JOHN'S COUNTY SO	07/07/2006	12:54:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST JOHN'S COUNTY SO	09/12/2006	22:53:17	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001137

Location	Date	Time	Source
FLAGLER COUNTY SO	04/04/2006	14:52:00	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-001138

Location	Date	Time	Source
FLAGLER COUNTY SO	04/05/2006	10:44:46	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FLAGLER COUNTY SO	05/01/2006	14:48:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FLAGLER COUNTY SO	05/02/2006	15:44:52	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001149

Location	Date	Time	Source
LAKE HELEN PD	04/08/2006	01:56:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LAKE HELEN PD	05/02/2006	01:17:46	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001150

Location	Date	Time	Source
MANATEE COUNTY SO	02/13/2006	16:23:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	04/10/2006	10:20:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MANATEE COUNTY SO	04/14/2006	17:23:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MANATEE COUNTY SO	04/14/2006	21:04:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001150

Location	Date	Time	Source
MANATEE COUNTY SO	04/14/2006	21:04:12	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MANATEE COUNTY SO	04/14/2006	21:25:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MANATEE COUNTY SO	04/14/2006	21:32:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	07/29/2006	00:17:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	07/29/2006	02:34:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001150

Location	Date	Time	Source
MANATEE COUNTY SO	07/29/2006	02:34:00	Local Diagnostic
	Test	Result	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001153

Location	Date	Time	Source
LEON COUNTY SO	03/22/2006	14:00:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LEON COUNTY SO	03/22/2006	14:01:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LEON COUNTY SO	04/06/2006	22:23:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEON COUNTY SO	04/13/2006	19:20:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001153

Location	Date	Time	Source
LEON COUNTY SO	04/13/2006	19:20:42	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEON COUNTY SO	05/31/2006	13:11:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEON COUNTY SO	06/01/2006	08:59:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LEON COUNTY SO	06/01/2006	09:00:32	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LEON COUNTY SO	06/01/2006	09:03:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001153

Location	Date	Time	Source
LEON COUNTY SO	06/01/2006	09:03:47	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEON COUNTY SO	06/01/2006	09:05:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEON COUNTY SO	06/01/2006	11:50:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LEON COUNTY SO	08/29/2006	16:42:31	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-001153

Location	Date	Time	Source
LEON COUNTY SO	08/29/2006	16:42:31	Local Diagnostic
	Test	Result	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001155

Location	Date	Time	Source
EGLIN AFB PD	08/11/2006	17:20:32	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001156

Location	Date	Time	Source
ORMOND BEACH PD	03/27/2006	16:27:27	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ORMOND BEACH PD	05/23/2006	17:41:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ORMOND BEACH PD	05/23/2006	17:42:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ORMOND BEACH PD	05/23/2006	17:49:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001156

Location	Date	Time	Source
ORMOND BEACH PD	05/23/2006	17:49:10	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001157

Location	Date	Time	Source
LAKE WALES PD	07/18/2006	14:03:45	Local Diagnostic

Test	Result
Voltage/Current Test	OK
RAM Test	OK
EEPROM Checksum Test	OK
Real Time Clock Test	OK
DSP Test	OK
Analytical Stability Test	OK
Internal Printer Test	OK
Modem Test	OK
Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001158

Location	Date	Time	Source
PONCE INLET P.D.	11/06/2006	10:37:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PONCE INLET P.D.	11/17/2006	20:11:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001159

Location	Date	Time	Source
ORANGE CITY PD	04/25/2006	08:37:26	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY PD	04/25/2006	09:40:13	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	11/17/2006	11:16:46	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	12/11/2006	13:01:57	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001159

Location	Date	Time	Source
ORANGE CITY P.D.	12/11/2006	13:01:57	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001174

Location	Date	Time	Source
CLERMONT PD	03/20/2006	16:43:15	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
CLERMONT PD	03/20/2006	16:45:26	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
CLERMONT PD	03/20/2006	17:05:32	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLERMONT PD	04/13/2006	12:18:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001174

Location	Date	Time	Source
CLERMONT PD	04/13/2006	12:18:48	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
CLERMONT PD	04/13/2006	18:35:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001202

Location	Date	Time	Source
COLLIER COUNTY SO	03/27/2006	05:04:53	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
COLLIER COUNTY SO	09/05/2006	18:20:31	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001203

Location	Date	Time	Source
GREENACRES P S	03/24/2006	13:55:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GREENACRES P S	03/24/2006	13:58:28	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GREENACRES P S	05/01/2006	07:52:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GREENACRES P S	11/04/2006	07:54:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	03/02/2006	09:56:40	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
LEE COUNTY SO	09/01/2006	20:55:36	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
LEE COUNTY SO	09/01/2006	21:10:17	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
LEE COUNTY SO	09/01/2006	21:10:51	Local Diagnostic
	Test	Result	
	Voltage/Current Test	Fail	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	09/01/2006	21:10:51	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	21:11:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	21:11:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	Fail
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	21:12:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	21:12:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	09/01/2006	21:12:51	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	21:56:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	21:57:14	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	21:57:52	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	09/01/2006	21:57:52	Local Diagnostic
		Test	Result
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	21:58:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	21:59:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	22:09:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	22:19:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	09/01/2006	22:19:11	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	22:19:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	09/01/2006	22:20:27	Local Diagnostic
		Test	Result
		Voltage/Current Test	Fail
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LEE COUNTY SO	09/01/2006	22:21:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	09/01/2006	22:21:10	Local Diagnostic
	Test	Result	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001230

Location	Date	Time	Source
TYNDALL AFB	11/02/2006	09:07:17	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	12/09/2006	09:39:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
TYNDALL AFB	12/09/2006	09:54:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	12/09/2006	10:04:46	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001230

Location	Date	Time	Source
TYNDALL AFB	12/09/2006	10:04:46	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	12/09/2006	11:51:35	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001233

Location	Date	Time	Source
PALM BEACH CO SO BG	03/18/2006	12:14:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO BG	03/18/2006	12:15:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001234

Location	Date	Time	Source
PALM BEACH SO BG	04/11/2006	13:00:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001237

Location	Date	Time	Source
POLK COUNTY SO	02/13/2006	10:24:49	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-001238

Location	Date	Time	Source
GROVELAND PD	06/22/2006	14:16:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GROVELAND PD	06/22/2006	14:17:28	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001244

Location	Date	Time	Source
PUTNAM COUNTY SO	04/10/2006	14:31:35	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PUTNAM COUNTY SO	04/10/2006	14:49:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001245

Location	Date	Time	Source
PORT ORANGE PD	08/10/2006	12:04:36	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001248

Location	Date	Time	Source
BROWARD COUNTY SO	03/28/2006	11:04:58	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
BROWARD COUNTY SO	04/21/2006	23:42:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001255

Location	Date	Time	Source
ORANGE COUNTY SO	07/11/2006	11:43:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ORANGE COUNTY SO	09/13/2006	08:23:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
ORANGE COUNTY SO	09/13/2006	08:41:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001257

Location	Date	Time	Source
ORANGE COUNTY SO	07/11/2006	12:05:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ORANGE COUNTY SO	07/11/2006	12:07:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001258

Location	Date	Time	Source
ORANGE COUNTY SO	07/11/2006	12:37:57	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001259

Location	Date	Time	Source
PINELLAS COUNTY SO	04/14/2006	22:21:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	08/26/2006	20:11:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001260

Location	Date	Time	Source
COCOA P.D.	01/17/2006	09:19:16	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	Fail		

Diagnostic Tests

Instrument Serial #: 80-001261

Location	Date	Time	Source
ROCKLEDGE PD	03/26/2006	20:49:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ROCKLEDGE PD	03/26/2006	22:38:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ROCKLEDGE PD	03/26/2006	22:39:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001262

Location	Date	Time	Source
MELBOURNE PD	12/01/2006	18:56:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MELBOURNE PD	12/02/2006	00:48:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MELBOURNE PD	12/02/2006	03:15:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001267

Location	Date	Time	Source
PALM BEACH CO SO	01/12/2006	11:28:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
PALM BEACH CO SO	07/17/2006	15:20:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	12/14/2006	14:44:07	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001268

Location	Date	Time	Source
PALM BEACH CO SO	12/13/2006	22:51:32	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	12/13/2006	22:53:14	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	12/13/2006	22:55:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	12/13/2006	22:56:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001268

Location	Date	Time	Source
PALM BEACH CO SO	12/13/2006	22:56:12	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	12/13/2006	23:33:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	12/15/2006	12:16:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	12/15/2006	12:18:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	12/15/2006	12:23:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001268

Location	Date	Time	Source
PALM BEACH CO SO	12/15/2006	12:23:23	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	12/15/2006	13:00:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	12/15/2006	16:51:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
PALM BEACH CO SO	12/15/2006	17:10:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-001268

Location	Date	Time	Source
PALM BEACH CO SO	12/15/2006	17:10:02	Local Diagnostic
		Test	Result
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	12/15/2006	17:22:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001269

Location	Date	Time	Source
PALM BEACH CO SO	06/21/2006	12:27:56	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001271

Location	Date	Time	Source
SEMINOLE SO	03/27/2006	00:15:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SEMINOLE SO	03/27/2006	01:16:07	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001272

Location	Date	Time	Source
SEMINOLE SO	03/27/2006	02:51:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SEMINOLE SO	04/28/2006	00:29:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SEMINOLE SO	05/13/2006	22:33:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SEMINOLE SO	07/28/2006	22:32:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001272

Location	Date	Time	Source
SEMINOLE SO	07/28/2006	22:32:49	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-001273

Location	Date	Time	Source
PINELLAS COUNTY SO	07/11/2006	05:03:03	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001274

Location	Date	Time	Source
PINELLAS COUNTY SO	05/12/2006	19:33:42	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
PINELLAS COUNTY SO	07/28/2006	03:28:33	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
PINELLAS COUNTY SO	07/28/2006	03:48:41	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
PINELLAS COUNTY SO	08/19/2006	21:39:24	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001274

Location	Date	Time	Source
PINELLAS COUNTY SO	08/19/2006	21:39:24	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
PINELLAS COUNTY SO	08/26/2006	20:14:26	Local Diagnostic
		Test	Result
		Voltage/Current Test	Fail
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	08/30/2006	14:30:55	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001276

Location	Date	Time	Source
MIAMI-DADE PD	02/21/2006	10:59:00	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001280

Location	Date	Time	Source
JACKSONVILLE SO	10/13/2006	08:22:30	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-001281

Location	Date	Time	Source
NASSAU COUNTY SO	03/21/2006	09:15:50	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001283

Location	Date	Time	Source
HIGH SPRINGS PD	05/28/2006	22:04:34	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001284

Location	Date	Time	Source
GILCHRIST COUNTY SO	04/11/2006	13:58:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GILCHRIST COUNTY SO	09/02/2006	08:17:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001285

Location	Date	Time	Source
GILCHRIST COUNTY SO	07/23/2006	12:13:29	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001286

Location	Date	Time	Source
BAKER COUNTY SO	09/26/2006	18:23:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
BAKER COUNTY SO	12/25/2006	03:44:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
BAKER COUNTY SO	12/25/2006	04:09:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001287

Location	Date	Time	Source
BAKER COUNTY SO	09/26/2006	18:30:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
BAKER COUNTY SO	09/26/2006	20:24:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001290

Location	Date	Time	Source
STARKE PD	10/30/2006	08:28:50	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001293

Location	Date	Time	Source
WILLISTON PD	06/05/2006	01:16:35	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
WILLISTON PD	06/07/2006	11:30:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001302

Location	Date	Time	Source
SANTA ROSA COUNTY SO	03/26/2006	22:57:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
SANTA ROSA COUNTY SO	03/26/2006	23:01:08	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
SANTA ROSA COUNTY SO	03/26/2006	23:05:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
SANTA ROSA COUNTY SO	03/26/2006	23:31:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001302

Location	Date	Time	Source
SANTA ROSA COUNTY SO	03/26/2006	23:31:16	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	07/08/2006	04:27:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	09/07/2006	11:29:58	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	10/13/2006	01:47:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	11/15/2006	23:39:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001302

Location	Date	Time	Source
SANTA ROSA COUNTY SO	11/15/2006	23:39:06	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	12/07/2006	02:42:25	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	12/07/2006	03:42:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001303

Location	Date	Time	Source
SANTA ROSA COUNTY SO	03/27/2006	04:27:56	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	07/08/2006	02:07:08	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	07/10/2006	02:19:52	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	09/07/2006	09:44:27	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001303

Location	Date	Time	Source
SANTA ROSA COUNTY SO	09/07/2006	09:44:27	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	10/12/2006	22:36:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001305

Location	Date	Time	Source
MARIANNA PD	12/24/2006	15:46:22	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	Fail		

Diagnostic Tests

Instrument Serial #: 80-001309

Location	Date	Time	Source
BAY COUNTY SO	03/27/2006	06:52:28	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
BAY COUNTY SO	03/27/2006	11:49:56	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001312

Location	Date	Time	Source
WALTON COUNTY SO	06/13/2006	23:17:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
WALTON COUNTY SO	07/30/2006	15:00:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
WALTON COUNTY SO	07/30/2006	15:00:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
WALTON COUNTY SO	07/30/2006	15:03:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001313

Location	Date	Time	Source
SPRINGFIELD PD	03/28/2006	02:34:46	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001320

Location	Date	Time	Source
OKEECHOBEE COUNTY SO	03/27/2006	08:30:06	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001321

Location	Date	Time	Source
OKEECHOBEE SO	03/27/2006	08:40:34	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001322

Location	Date	Time	Source
OKEECHOBEE PD	04/20/2006	07:17:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OKEECHOBEE PD	05/09/2006	09:08:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OKEECHOBEE PD	06/24/2006	07:31:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OKEECHOBEE PD	08/29/2006	06:54:46	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001322

Location	Date	Time	Source
OKEECHOBEE PD	08/29/2006	06:54:46	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OKEECHOBEE PD	09/29/2006	07:20:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OKEECHOBEE PD	11/12/2006	09:16:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001328

Location	Date	Time	Source
INDIAN RIVER CO SO	03/28/2006	12:35:39	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001329

Location	Date	Time	Source
INDIAN RIVER CO SO	03/28/2006	11:27:07	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
INDIAN RIVER CO SO	03/28/2006	12:53:25	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001344

Location	Date	Time	Source
SARASOTA COUNTY SO	03/02/2006	16:34:36	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SARASOTA COUNTY SO	08/28/2006	09:19:45	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SARASOTA COUNTY SO	08/28/2006	10:12:10	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SARASOTA COUNTY SO	08/29/2006	13:44:08	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001344

Location	Date	Time	Source
SARASOTA COUNTY SO	08/29/2006	13:44:08	Local Diagnostic
		Test	Result
		Internal Printer Test	Fail
		Modem Test	Fail
		Temperature Regulation Test	OK
SARASOTA COUNTY SO	12/08/2006	13:47:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001347

Location	Date	Time	Source
SARASOTA COUNTY SO	08/28/2006	10:52:33	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001348

Location	Date	Time	Source
SARASOTA COUNTY SO	03/02/2006	16:33:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SARASOTA COUNTY SO	10/16/2006	09:15:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SARASOTA COUNTY SO	10/16/2006	09:32:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001350

Location	Date	Time	Source
FRUITLAND PARK PD	04/17/2006	17:16:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FRUITLAND PARK PD	05/02/2006	17:24:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001360

Location	Date	Time	Source
EVERGLADES NAT. PARK	03/10/2006	12:52:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
EVERGLADES NAT. PARK	04/25/2006	14:37:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001361

Location	Date	Time	Source
FL HIGHWAY PATROL	04/02/2006	12:53:49	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001363

Location	Date	Time	Source
CHARLOTTE COUNTY SO	02/15/2006	16:31:25	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CHARLOTTE COUNTY SO	07/30/2006	18:58:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
CHARLOTTE COUNTY SO	07/30/2006	19:08:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CHARLOTTE COUNTY SO	08/02/2006	17:27:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001363

Location	Date	Time	Source
CHARLOTTE COUNTY SO	08/02/2006	17:27:44	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001367

Location	Date	Time	Source
PINELLAS COUNTY SO	04/02/2006	03:46:08	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001418

Location	Date	Time	Source
ORANGE COUNTY SO	07/11/2006	12:47:17	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ORANGE COUNTY SO	08/21/2006	09:10:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001420

Location	Date	Time	Source
ORANGE COUNTY SO	06/23/2006	12:26:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ORANGE COUNTY SO	07/11/2006	09:07:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ORANGE COUNTY SO	07/11/2006	09:52:58	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001440

Location	Date	Time	Source
KENNEDY SPACE CENTER	04/28/2006	01:00:28	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001443

Location	Date	Time	Source
CLAY COUNTY SO	05/06/2006	03:33:24	Local Diagnostic

Test	Result
Voltage/Current Test	OK
RAM Test	OK
EEPROM Checksum Test	OK
Real Time Clock Test	OK
DSP Test	OK
Analytical Stability Test	OK
Internal Printer Test	OK
Modem Test	OK
Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001471

Location	Date	Time	Source
PATRICK AFB	07/03/2006	10:50:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
PATRICK AFB	08/23/2006	11:30:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PATRICK AFB	09/20/2006	10:32:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001646

Location	Date	Time	Source
BAY COUNTY SO	03/27/2006	06:45:34	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-001649

Location	Date	Time	Source
KENNETH CITY PD	10/18/2006	00:23:13	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001715

Location	Date	Time	Source
OSCEOLA CORRECTIONS	07/28/2006	23:02:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
OSCEOLA CORRECTIONS	11/06/2006	15:17:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
OSCEOLA CORRECTIONS	11/06/2006	15:17:56	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
OSCEOLA CORRECTIONS	11/07/2006	11:22:27	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001715

Location	Date	Time	Source
OSCEOLA CORRECTIONS	11/07/2006	11:22:27	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
OSCEOLA CORRECTIONS	11/07/2006	11:25:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
OSCEOLA CORRECTIONS	11/07/2006	11:32:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
OSCEOLA CORRECTIONS	11/07/2006	12:20:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001720

Location	Date	Time	Source
LAKE WALES PD	06/01/2006	09:43:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LAKE WALES PD	06/01/2006	09:44:26	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LAKE WALES PD	06/01/2006	09:48:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001721

Location	Date	Time	Source
CMI INC	08/10/2006	15:36:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
CMI INC	08/14/2006	13:15:33	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CMI INC	08/14/2006	13:38:58	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CMI INC	08/17/2006	08:08:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001721

Location	Date	Time	Source
CMI INC	08/17/2006	08:08:29	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001731

Location	Date	Time	Source
HILLSBOROUGH SO	07/27/2006	22:26:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	11/02/2006	14:36:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	11/10/2006	20:58:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001739

Location	Date	Time	Source
CHARLOTTE COUNTY SO	05/26/2006	22:48:45	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-001741

Location	Date	Time	Source
PALM BEACH SO	07/17/2006	12:35:25	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	10/16/2006	22:48:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-002231

Location	Date	Time	Source
NEW SYMRNA BEACH PD	10/20/2006	12:10:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
NEW SYMRNA BEACH PD	10/24/2006	11:39:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-002232

Location	Date	Time	Source
MIAMI BEACH PD	11/27/2006	06:01:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	11/27/2006	11:28:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail