

Florida Department of Law Enforcement

Diagnostic Tests

Instrument Serial #: 80-000219

Location	Date	Time	Source
FDLE FMROC	01/08/2007	16:13:32	Local Diagnostic

Test	Result
Voltage/Current Test	OK
RAM Test	OK
EEPROM Checksum Test	OK
Real Time Clock Test	OK
DSP Test	OK
Analytical Stability Test	OK
Internal Printer Test	OK
Modem Test	OK
Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000227

Location	Date	Time	Source
FDLE OROC	01/17/2007	16:21:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FDLE OROC	01/17/2007	16:24:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FDLE OROC	03/13/2007	16:10:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000228

Location	Date	Time	Source
FDLE MROC	07/24/2007	10:09:06	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000737

Location	Date	Time	Source
ALACHUA COUNTY SO	07/27/2007	14:27:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ALACHUA COUNTY SO	07/31/2007	11:58:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ALACHUA COUNTY SO	08/09/2007	13:40:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000739

Location	Date	Time	Source
OKALOOSA COUNTY SO	07/30/2007	05:02:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
OKALOOSA COUNTY SO	07/30/2007	05:02:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
OKALOOSA COUNTY SO	07/30/2007	05:04:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000760

Location	Date	Time	Source
ALACHUA COUNTY SO	10/15/2007	14:41:42	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-000763

Location	Date	Time	Source
OKALOOSA COUNTY SO	09/27/2007	22:27:51	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000765

Location	Date	Time	Source
SANTA ROSA CO SO	01/05/2007	22:41:29	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA CO SO	03/09/2007	22:37:44	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA CO SO	04/07/2007	00:29:29	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA CO SO	05/05/2007	01:29:44	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000765

Location	Date	Time	Source
SANTA ROSA CO SO	05/05/2007	01:29:44	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	06/01/2007	23:53:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	06/19/2007	03:36:52	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	07/06/2007	22:10:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	08/11/2007	01:29:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-000765

Location	Date	Time	Source
SANTA ROSA CO SO	08/11/2007	01:29:59	Local Diagnostic
	Test	Result	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA CO SO	09/14/2007	22:46:52	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA CO SO	10/22/2007	12:43:36	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA CO SO	11/03/2007	00:00:24	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000765

Location	Date	Time	Source
SANTA ROSA CO SO	11/03/2007	00:00:24	Local Diagnostic
		Test	Result
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	12/08/2007	12:08:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000771

Location	Date	Time	Source
PERRY PD	04/26/2007	01:13:33	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PERRY PD	10/30/2007	09:45:33	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000772

Location	Date	Time	Source
SANTA ROSA CO SO	01/20/2007	01:51:41	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA CO SO	02/03/2007	00:16:41	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA CO SO	03/09/2007	23:07:59	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA CO SO	03/15/2007	00:46:02	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000772

Location	Date	Time	Source
SANTA ROSA CO SO	03/15/2007	00:46:02	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	04/07/2007	00:22:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	05/05/2007	00:58:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	06/01/2007	23:25:27	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	06/19/2007	03:35:08	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-000772

Location	Date	Time	Source
SANTA ROSA CO SO	06/19/2007	03:35:08	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	07/06/2007	22:32:09	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	08/11/2007	01:15:09	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA CO SO	09/14/2007	23:23:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-000772

Location	Date	Time	Source
SANTA ROSA CO SO	09/14/2007	23:23:24	Local Diagnostic
	Test	Result	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA CO SO	10/22/2007	11:54:51	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA CO SO	11/02/2007	23:30:29	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA COUNTY SO	11/20/2007	17:46:42	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000785

Location	Date	Time	Source
HOLMES COUNTY SO	04/30/2007	13:27:56	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000795

Location	Date	Time	Source
GULF COUNTY SO	08/29/2007	09:26:09	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000808

Location	Date	Time	Source
HILLSBOROUGH SO	01/19/2007	22:24:41	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-000812

Location	Date	Time	Source
HERNANDO COUNTY SO	05/10/2007	14:41:57	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
HERNANDO COUNTY SO	06/11/2007	10:56:56	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	
HERNANDO COUNTY SO	06/11/2007	10:57:42	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	
HERNANDO COUNTY SO	06/11/2007	11:01:55	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000812

Location	Date	Time	Source
HERNANDO COUNTY SO	06/11/2007	11:01:55	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HERNANDO COUNTY SO	07/02/2007	11:19:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HERNANDO COUNTY SO	10/24/2007	15:07:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000813

Location	Date	Time	Source
MARION COUNTY SO	06/07/2007	12:59:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MARION COUNTY SO	06/27/2007	20:03:09	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000817

Location	Date	Time	Source
CITRUS COUNTY SO	11/13/2007	15:27:17	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CITRUS COUNTY SO	12/18/2007	13:00:52	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CITRUS COUNTY SO	12/18/2007	13:56:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CITRUS COUNTY SO	12/20/2007	09:59:26	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000817

Location	Date	Time	Source
CITRUS COUNTY SO	12/20/2007	09:59:26	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000819

Location	Date	Time	Source
CITRUS COUNTY SO	05/10/2007	16:42:56	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CITRUS COUNTY SO	10/25/2007	10:35:06	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CITRUS COUNTY SO	10/25/2007	11:18:50	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CITRUS COUNTY SO	11/12/2007	11:18:58	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000819

Location	Date	Time	Source
CITRUS COUNTY SO	11/12/2007	11:18:58	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CITRUS COUNTY SO	11/30/2007	09:57:16	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CITRUS COUNTY SO	11/30/2007	10:49:42	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CITRUS COUNTY SO	12/18/2007	15:03:35	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CITRUS COUNTY SO	12/18/2007	17:24:21	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000819

Location	Date	Time	Source
CITRUS COUNTY SO	12/18/2007	17:24:21	Local Diagnostic
	Test	Result	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000822

Location	Date	Time	Source
LAKE S.O.	08/28/2007	08:42:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LAKE S.O.	08/28/2007	08:58:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LAKE S.O.	10/01/2007	09:39:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000824

Location	Date	Time	Source
LEESBURG P.D.	09/28/2007	12:54:58	Remote Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-000825

Location	Date	Time	Source
MOUNT DORA P.D.	02/28/2007	18:45:15	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000827

Location	Date	Time	Source
MARION COUNTY SO	11/18/2007	13:10:49	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000829

Location	Date	Time	Source
HILLSBOROUGH SO	04/03/2007	09:14:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	11/04/2007	16:00:45	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000830

Location	Date	Time	Source
HILLSBOROUGH SO	04/03/2007	15:10:39	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
HILLSBOROUGH SO	04/04/2007	10:01:37	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
HILLSBOROUGH SO	04/04/2007	11:49:15	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
HILLSBOROUGH SO	05/01/2007	16:16:58	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000830

Location	Date	Time	Source
HILLSBOROUGH SO	05/01/2007	16:16:58	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	05/01/2007	17:12:15	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	12/04/2007	15:09:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	12/04/2007	16:44:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000833

Location	Date	Time	Source
HILLSBOROUGH SO	01/28/2007	09:57:29	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
HILLSBOROUGH SO	10/19/2007	16:09:33	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
HILLSBOROUGH SO	10/22/2007	11:13:23	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
HILLSBOROUGH SO	10/22/2007	13:11:18	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000833

Location	Date	Time	Source
HILLSBOROUGH SO	10/22/2007	13:11:18	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	10/22/2007	13:49:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	10/23/2007	08:50:09	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	10/23/2007	08:51:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	10/23/2007	13:25:05	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-000833

Location	Date	Time	Source
HILLSBOROUGH SO	10/23/2007	13:25:05	Local Diagnostic
	Test	Result	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000861

Location	Date	Time	Source
SARASOTA COUNTY SO	05/25/2007	23:03:05	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000867

Location	Date	Time	Source
MONROE COUNTY S.O.	11/23/2007	21:14:37	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-000868

Location	Date	Time	Source
MONROE COUNTY SO	09/24/2007	10:13:26	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000872

Location	Date	Time	Source
MIAMI PD	07/18/2007	16:10:06	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000876

Location	Date	Time	Source
HIALEAH PD	09/10/2007	15:19:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	Fail
		Modem Test	OK
		Temperature Regulation Test	Fail
HIALEAH PD	09/10/2007	15:40:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HIALEAH PD	09/11/2007	12:57:58	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
HIALEAH PD	09/11/2007	15:08:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000876

Location	Date	Time	Source
HIALEAH PD	09/11/2007	15:08:16	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000879

Location	Date	Time	Source
MIAMI BEACH PD	01/05/2007	00:05:05	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	01/05/2007	00:08:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	01/05/2007	00:09:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	01/05/2007	00:10:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000879

Location	Date	Time	Source
MIAMI BEACH PD	01/05/2007	00:10:06	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	01/05/2007	00:12:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	01/05/2007	00:15:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	01/05/2007	00:16:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	01/08/2007	00:27:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-000879

Location	Date	Time	Source
MIAMI BEACH PD	01/08/2007	00:27:39	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MIAMI BEACH PD	04/25/2007	03:08:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI BEACH PD	09/11/2007	09:02:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI BEACH PD	10/25/2007	12:20:17	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-000879

Location	Date	Time	Source
MIAMI BEACH PD	10/25/2007	12:20:17	Local Diagnostic
		Test	Result
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI BEACH PD	11/20/2007	11:29:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	Fail
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI BEACH PD	11/20/2007	11:30:53	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000883

Location	Date	Time	Source
MIAMI-DADE PD	07/30/2007	14:10:32	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000887

Location	Date	Time	Source
CHATTAHOOCHEE PD	01/15/2007	11:07:55	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CHATTAHOOCHEE PD	02/12/2007	09:40:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000888

Location	Date	Time	Source
PINELLAS COUNTY SO	09/15/2007	01:46:36	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-000889

Location	Date	Time	Source
PINELLAS COUNTY SO	09/20/2007	00:39:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	12/12/2007	22:00:05	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	12/13/2007	00:50:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000890

Location	Date	Time	Source
PINELLAS COUNTY SO	11/23/2007	19:27:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	11/26/2007	14:20:26	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	11/26/2007	14:21:07	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	11/26/2007	14:23:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000890

Location	Date	Time	Source
PINELLAS COUNTY SO	11/26/2007	14:23:51	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	11/26/2007	14:24:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	11/26/2007	14:25:13	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000893

Location	Date	Time	Source
FFWCC (LAKE CITY)	09/28/2007	17:27:23	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000905

Location	Date	Time	Source
FWCC - NORTHEAST	10/23/2007	14:25:53	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FWCC - NORTHEAST	10/23/2007	14:26:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FWCC - NORTHEAST	10/23/2007	14:27:56	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000906

Location	Date	Time	Source
FISH & WILDLIFE CC	10/23/2007	13:54:00	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000909

Location	Date	Time	Source
PINECREST PD	10/16/2007	10:45:29	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000912

Location	Date	Time	Source
MANATEE COUNTY SO	06/05/2007	11:01:07	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	06/05/2007	11:03:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MANATEE COUNTY SO	06/05/2007	11:17:35	Remote Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000937

Location	Date	Time	Source
SANIBEL PD	08/26/2007	15:07:40	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000941

Location	Date	Time	Source
COLLIER COUNTY SO	12/16/2007	02:52:58	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000943

Location	Date	Time	Source
COLLIER COUNTY SO	07/31/2007	15:14:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
COLLIER COUNTY SO	07/31/2007	15:15:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-000944

Location	Date	Time	Source
COLLIER COUNTY SO	12/25/2007	09:37:14	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000945

Location	Date	Time	Source
CHARLOTTE COUNTY SO	08/10/2007	19:33:15	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000946

Location	Date	Time	Source
CHARLOTTE COUNTY SO	02/10/2007	19:28:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CHARLOTTE COUNTY SO	08/30/2007	14:41:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000949

Location	Date	Time	Source
TALLAHASSEE PD	04/06/2007	22:57:51	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000950

Location	Date	Time	Source
HAVANA POLICE DEPT	04/24/2007	15:15:49	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-000952

Location	Date	Time	Source
FRANKLIN COUNTY SO	04/17/2007	16:30:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FRANKLIN COUNTY SO	04/17/2007	16:31:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FRANKLIN COUNTY SO	04/17/2007	16:31:46	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000960

Location	Date	Time	Source
LIBERTY COUNTY SO	07/03/2007	16:22:37	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LIBERTY COUNTY SO	07/17/2007	14:21:32	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LIBERTY COUNTY SO	07/17/2007	14:22:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LIBERTY COUNTY SO	07/30/2007	14:15:09	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-000960

Location	Date	Time	Source
LIBERTY COUNTY SO	07/30/2007	14:15:09	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000967

Location	Date	Time	Source
APOPKA P.D.	12/06/2007	11:42:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
APOPKA P.D.	12/06/2007	12:04:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	Fail
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-000994

Location	Date	Time	Source
WINTER PARK P.D.	09/25/2007	15:14:12	Remote Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-000998

Location	Date	Time	Source
SEMINOLE S.O.	03/17/2007	21:34:43	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001003

Location	Date	Time	Source
PINELLAS COUNTY SO	12/26/2007	17:12:07	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001006

Location	Date	Time	Source
INDIALANTIC PD	02/28/2007	02:28:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
INDIALANTIC PD	02/28/2007	02:34:31	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
INDIALANTIC PD	02/28/2007	02:35:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
INDIALANTIC PD	02/28/2007	02:41:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001006

Location	Date	Time	Source
INDIALANTIC PD	02/28/2007	02:41:19	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
INDIALANTIC PD	02/28/2007	02:43:32	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
INDIALANTIC PD	02/28/2007	02:44:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
INDIALANTIC PD	07/26/2007	01:13:13	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
INDIALANTIC PD	09/19/2007	02:35:27	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001006

Location	Date	Time	Source
INDIALANTIC PD	09/19/2007	02:35:27	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
INDIALANTIC PD	09/19/2007	02:36:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
INDIALANTIC PD	12/16/2007	08:52:53	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001008

Location	Date	Time	Source
WEST MELBOURNE PD	01/25/2007	21:47:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
WEST MELBOURNE PD	08/09/2007	09:34:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001018

Location	Date	Time	Source
JACKSONVILLE SO	04/02/2007	10:37:59	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
JACKSONVILLE SO	04/30/2007	05:48:48	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	
JACKSONVILLE SO	04/30/2007	05:49:58	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	
JACKSONVILLE SO	06/18/2007	13:57:44	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001018

Location	Date	Time	Source
JACKSONVILLE SO	06/18/2007	13:57:44	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001046

Location	Date	Time	Source
CLAY COUNTY SO	01/15/2007	04:12:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLAY COUNTY SO	03/07/2007	03:16:31	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLAY COUNTY SO	03/19/2007	08:41:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLAY COUNTY SO	03/19/2007	08:46:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001046

Location	Date	Time	Source
CLAY COUNTY SO	03/19/2007	08:46:50	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CLAY COUNTY SO	07/28/2007	22:28:00	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CLAY COUNTY SO	09/14/2007	10:04:57	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001049

Location	Date	Time	Source
PASCO COUNTY SO	09/13/2007	19:01:32	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001050

Location	Date	Time	Source
CORAL SPRINGS PD	08/30/2007	08:26:49	Local Diagnostic
Test		Result	
Voltage/Current Test		OK	
RAM Test		OK	
EEPROM Checksum Test		OK	
Real Time Clock Test		OK	
DSP Test		OK	
Analytical Stability Test		OK	
Internal Printer Test		OK	
Modem Test		OK	
Temperature Regulation Test		OK	

Diagnostic Tests

Instrument Serial #: 80-001052

Location	Date	Time	Source
JACKSONVILLE SO	01/23/2007	14:41:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
JACKSONVILLE SO	02/20/2007	11:09:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001053

Location	Date	Time	Source
NASSAU CO SO	06/20/2007	06:13:04	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001055

Location	Date	Time	Source
POLK COUNTY SO	12/03/2007	14:06:26	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
POLK COUNTY SO	12/03/2007	14:55:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001057

Location	Date	Time	Source
LAKELAND PD	03/05/2007	13:54:55	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001060

Location	Date	Time	Source
WINTER HAVEN PD	09/20/2007	10:00:28	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001062

Location	Date	Time	Source
TREASURE ISLAND PD	02/05/2007	09:34:03	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001063

Location	Date	Time	Source
HOLLYWOOD PD	07/23/2007	12:32:17	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			OK

Diagnostic Tests

Instrument Serial #: 80-001064

Location	Date	Time	Source
NEW PORT RICHEY PD	01/03/2007	10:10:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
NEW PORT RICHEY PD	01/04/2007	15:48:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
NEW PORT RICHEY PD	02/27/2007	10:45:49	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
NEW PORT RICHEY PD	02/27/2007	15:42:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001064

Location	Date	Time	Source
NEW PORT RICHEY PD	02/27/2007	15:42:34	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
NEW PORT RICHEY PD	02/28/2007	14:56:53	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
NEW PORT RICHEY PD	02/28/2007	16:15:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
NEW PORT RICHEY PD	06/07/2007	17:29:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
NEW PORT RICHEY PD	09/20/2007	02:37:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001064

Location	Date	Time	Source
NEW PORT RICHEY PD	09/20/2007	02:37:59	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
NEW PORT RICHEY PD	09/23/2007	15:05:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
NEW PORT RICHEY PD	11/01/2007	21:33:07	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001065

Location	Date	Time	Source
TARPON SPRINGS PD	08/07/2007	14:05:53	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
TARPON SPRINGS PD	08/07/2007	14:06:37	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
TARPON SPRINGS PD	08/07/2007	14:15:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
TARPON SPRINGS PD	12/17/2007	10:17:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001065

Location	Date	Time	Source
TARPON SPRINGS PD	12/17/2007	10:17:00	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001068

Location	Date	Time	Source
CLEARWATER PD	02/16/2007	14:27:01	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001070

Location	Date	Time	Source
FT MEADE PD	12/05/2007	10:24:59	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001071

Location	Date	Time	Source
CLAY COUNTY SO	03/19/2007	08:39:13	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CLAY COUNTY SO	06/16/2007	02:01:51	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
CLAY COUNTY SO	11/30/2007	19:19:35	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001074

Location	Date	Time	Source
PASCO COUNTY SO	04/25/2007	14:31:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PASCO COUNTY SO	04/25/2007	16:32:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001078

Location	Date	Time	Source
DUNDEE PD	08/29/2007	10:12:42	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001109

Location	Date	Time	Source
FL HIGHWAY PATROL	07/30/2007	12:03:15	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FL HIGHWAY PATROL	09/22/2007	14:56:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001112

Location	Date	Time	Source
FL HIGHWAY PATROL	11/04/2007	10:57:08	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-001113

Location	Date	Time	Source
FL HIGHWAY PATROL	03/06/2007	07:02:45	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
FL HIGHWAY PATROL	07/31/2007	18:45:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FL HIGHWAY PATROL	12/29/2007	00:51:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001116

Location	Date	Time	Source
EGLIN AFB POLICE	04/27/2007	23:44:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
EGLIN AFB POLICE	04/27/2007	23:47:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
EGLIN AFB POLICE	05/31/2007	02:31:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	Fail
		Temperature Regulation Test	OK
EGLIN AFB POLICE	05/31/2007	02:32:15	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001116

Location	Date	Time	Source
EGLIN AFB POLICE	05/31/2007	02:32:15	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	Fail
		Temperature Regulation Test	OK
EGLIN AFB POLICE	06/25/2007	13:12:09	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
EGLIN AFB POLICE	07/31/2007	09:18:51	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001119

Location	Date	Time	Source
FHP TROOP D - DELAND	07/26/2007	16:10:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP D - DELAND	07/31/2007	10:59:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP D - DELAND	08/29/2007	09:33:28	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FHP TROOP D - DELAND	11/13/2007	18:19:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001119

Location	Date	Time	Source
FHP TROOP D - DELAND	11/13/2007	18:19:21	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001120

Location	Date	Time	Source
FL HIGHWAY PATROL	08/28/2007	15:20:25	Local Diagnostic
Test	Result		
Voltage/Current Test	Fail		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	Fail		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	Fail		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001121

Location	Date	Time	Source
FHP TROOP E MIAMI	11/26/2007	23:18:34	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001128

Location	Date	Time	Source
PUTNAM COUNTY S.O.	01/15/2007	11:48:16	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001153

Location	Date	Time	Source
LEON COUNTY SO	02/27/2007	12:42:08	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
LEON COUNTY SO	02/27/2007	13:00:09	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001159

Location	Date	Time	Source
ORANGE CITY P.D.	01/10/2007	13:04:13	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	02/20/2007	10:36:06	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	03/15/2007	09:30:48	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	04/17/2007	12:39:06	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001159

Location	Date	Time	Source
ORANGE CITY P.D.	04/17/2007	12:39:06	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	05/20/2007	19:31:38	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	05/20/2007	21:57:16	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	05/21/2007	10:31:52	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	06/26/2007	19:31:44	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001159

Location	Date	Time	Source
ORANGE CITY P.D.	06/26/2007	19:31:44	Local Diagnostic
	Test	Result	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	07/25/2007	14:34:20	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	08/26/2007	18:58:57	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
ORANGE CITY P.D.	09/25/2007	10:16:44	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001159

Location	Date	Time	Source
ORANGE CITY P.D.	09/25/2007	10:16:44	Local Diagnostic
		Test	Result
		Modem Test	OK
		Temperature Regulation Test	OK
ORANGE CITY P.D.	10/20/2007	16:30:07	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ORANGE CITY P.D.	11/19/2007	07:23:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ORANGE CITY P.D.	12/25/2007	07:29:45	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001174

Location	Date	Time	Source
CLERMONT P.D.	04/17/2007	07:04:07	Local Diagnostic

Test	Result
Voltage/Current Test	OK
RAM Test	OK
EEPROM Checksum Test	OK
Real Time Clock Test	OK
DSP Test	OK
Analytical Stability Test	OK
Internal Printer Test	OK
Modem Test	OK
Temperature Regulation Test	Fail

CLERMONT P.D.	04/17/2007	07:18:41	Local Diagnostic
---------------	------------	----------	------------------

Test	Result
Voltage/Current Test	OK
RAM Test	OK
EEPROM Checksum Test	OK
Real Time Clock Test	OK
DSP Test	OK
Analytical Stability Test	OK
Internal Printer Test	OK
Modem Test	OK
Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001177

Location	Date	Time	Source
LADY LAKE P.D.	03/16/2007	16:19:33	Local Diagnostic

Test	Result
Voltage/Current Test	OK
RAM Test	OK
EEPROM Checksum Test	OK
Real Time Clock Test	OK
DSP Test	OK
Analytical Stability Test	OK
Internal Printer Test	OK
Modem Test	OK
Temperature Regulation Test	OK

LADY LAKE P.D.	03/16/2007	16:20:10	Local Diagnostic
----------------	------------	----------	------------------

Test	Result
Voltage/Current Test	OK
RAM Test	OK
EEPROM Checksum Test	OK
Real Time Clock Test	OK
DSP Test	OK
Analytical Stability Test	OK
Internal Printer Test	OK
Modem Test	OK
Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001179

Location	Date	Time	Source
MIAMI P.D.	11/10/2007	10:53:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI P.D.	11/10/2007	10:53:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001190

Location	Date	Time	Source
BOYNTON BEACH PD	01/22/2007	10:09:23	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001203

Location	Date	Time	Source
GREENACRES P S	07/24/2007	13:19:54	Remote Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GREENACRES P S	07/24/2007	13:22:34	Remote Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GREENACRES P S	07/24/2007	13:28:54	Remote Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GREENACRES P S	07/24/2007	13:30:58	Remote Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001203

Location	Date	Time	Source
GREENACRES P S	07/24/2007	13:30:58	Remote Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	07/18/2007	14:14:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	07/18/2007	14:15:31	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	07/18/2007	14:24:15	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	07/18/2007	14:24:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	Fail
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	07/18/2007	14:24:59	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	07/18/2007	14:25:37	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	07/18/2007	14:26:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	07/18/2007	14:27:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	07/18/2007	14:27:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	07/18/2007	14:27:44	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	07/18/2007	14:28:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	07/18/2007	14:29:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	07/18/2007	14:53:58	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	07/18/2007	14:53:58	Local Diagnostic
	Test	Result	
	Modem Test	OK	
	Temperature Regulation Test	OK	
LEE COUNTY SO	07/18/2007	14:54:39	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
LEE COUNTY SO	09/29/2007	01:23:09	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
LEE COUNTY SO	10/11/2007	13:15:27	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
LEE COUNTY SO	10/11/2007	13:16:14	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	10/11/2007	13:16:14	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	10/11/2007	13:16:55	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	10/16/2007	15:55:26	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
LEE COUNTY SO	10/16/2007	15:56:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-001208

Location	Date	Time	Source
LEE COUNTY SO	10/16/2007	15:56:12	Local Diagnostic
	Test	Result	
	Modem Test	OK	
	Temperature Regulation Test	OK	
LEE COUNTY SO	12/04/2007	15:24:55	Remote Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001230

Location	Date	Time	Source
TYNDALL AFB	01/31/2007	13:34:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
TYNDALL AFB	01/31/2007	13:37:05	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
TYNDALL AFB	01/31/2007	13:48:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	02/28/2007	05:37:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001230

Location	Date	Time	Source																				
TYNDALL AFB	02/28/2007	05:37:47	Local Diagnostic																				
		<table border="1" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Test</th> <th style="text-align: left;">Result</th> </tr> </thead> <tbody> <tr> <td>Internal Printer Test</td> <td>OK</td> </tr> <tr> <td>Modem Test</td> <td>OK</td> </tr> <tr> <td>Temperature Regulation Test</td> <td>OK</td> </tr> </tbody> </table>	Test	Result	Internal Printer Test	OK	Modem Test	OK	Temperature Regulation Test	OK													
Test	Result																						
Internal Printer Test	OK																						
Modem Test	OK																						
Temperature Regulation Test	OK																						
TYNDALL AFB	02/28/2007	05:44:02	Local Diagnostic																				
		<table border="1" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Test</th> <th style="text-align: left;">Result</th> </tr> </thead> <tbody> <tr> <td>Voltage/Current Test</td> <td>OK</td> </tr> <tr> <td>RAM Test</td> <td>OK</td> </tr> <tr> <td>EEPROM Checksum Test</td> <td>OK</td> </tr> <tr> <td>Real Time Clock Test</td> <td>OK</td> </tr> <tr> <td>DSP Test</td> <td>OK</td> </tr> <tr> <td>Analytical Stability Test</td> <td>OK</td> </tr> <tr> <td>Internal Printer Test</td> <td>OK</td> </tr> <tr> <td>Modem Test</td> <td>OK</td> </tr> <tr> <td>Temperature Regulation Test</td> <td>OK</td> </tr> </tbody> </table>	Test	Result	Voltage/Current Test	OK	RAM Test	OK	EEPROM Checksum Test	OK	Real Time Clock Test	OK	DSP Test	OK	Analytical Stability Test	OK	Internal Printer Test	OK	Modem Test	OK	Temperature Regulation Test	OK	
Test	Result																						
Voltage/Current Test	OK																						
RAM Test	OK																						
EEPROM Checksum Test	OK																						
Real Time Clock Test	OK																						
DSP Test	OK																						
Analytical Stability Test	OK																						
Internal Printer Test	OK																						
Modem Test	OK																						
Temperature Regulation Test	OK																						
TYNDALL AFB	03/30/2007	06:42:34	Local Diagnostic																				
		<table border="1" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Test</th> <th style="text-align: left;">Result</th> </tr> </thead> <tbody> <tr> <td>Voltage/Current Test</td> <td>OK</td> </tr> <tr> <td>RAM Test</td> <td>OK</td> </tr> <tr> <td>EEPROM Checksum Test</td> <td>OK</td> </tr> <tr> <td>Real Time Clock Test</td> <td>OK</td> </tr> <tr> <td>DSP Test</td> <td>OK</td> </tr> <tr> <td>Analytical Stability Test</td> <td>OK</td> </tr> <tr> <td>Internal Printer Test</td> <td>OK</td> </tr> <tr> <td>Modem Test</td> <td>OK</td> </tr> <tr> <td>Temperature Regulation Test</td> <td>OK</td> </tr> </tbody> </table>	Test	Result	Voltage/Current Test	OK	RAM Test	OK	EEPROM Checksum Test	OK	Real Time Clock Test	OK	DSP Test	OK	Analytical Stability Test	OK	Internal Printer Test	OK	Modem Test	OK	Temperature Regulation Test	OK	
Test	Result																						
Voltage/Current Test	OK																						
RAM Test	OK																						
EEPROM Checksum Test	OK																						
Real Time Clock Test	OK																						
DSP Test	OK																						
Analytical Stability Test	OK																						
Internal Printer Test	OK																						
Modem Test	OK																						
Temperature Regulation Test	OK																						
TYNDALL AFB	04/26/2007	06:12:37	Local Diagnostic																				
		<table border="1" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Test</th> <th style="text-align: left;">Result</th> </tr> </thead> <tbody> <tr> <td>Voltage/Current Test</td> <td>OK</td> </tr> <tr> <td>RAM Test</td> <td>OK</td> </tr> <tr> <td>EEPROM Checksum Test</td> <td>OK</td> </tr> <tr> <td>Real Time Clock Test</td> <td>OK</td> </tr> <tr> <td>DSP Test</td> <td>OK</td> </tr> <tr> <td>Analytical Stability Test</td> <td>OK</td> </tr> <tr> <td>Internal Printer Test</td> <td>OK</td> </tr> <tr> <td>Modem Test</td> <td>OK</td> </tr> <tr> <td>Temperature Regulation Test</td> <td>OK</td> </tr> </tbody> </table>	Test	Result	Voltage/Current Test	OK	RAM Test	OK	EEPROM Checksum Test	OK	Real Time Clock Test	OK	DSP Test	OK	Analytical Stability Test	OK	Internal Printer Test	OK	Modem Test	OK	Temperature Regulation Test	OK	
Test	Result																						
Voltage/Current Test	OK																						
RAM Test	OK																						
EEPROM Checksum Test	OK																						
Real Time Clock Test	OK																						
DSP Test	OK																						
Analytical Stability Test	OK																						
Internal Printer Test	OK																						
Modem Test	OK																						
Temperature Regulation Test	OK																						
TYNDALL AFB	05/30/2007	07:47:14	Local Diagnostic																				
		<table border="1" style="width: 100%;"> <thead> <tr> <th style="text-align: left;">Test</th> <th style="text-align: left;">Result</th> </tr> </thead> <tbody> <tr> <td>Voltage/Current Test</td> <td>OK</td> </tr> </tbody> </table>	Test	Result	Voltage/Current Test	OK																	
Test	Result																						
Voltage/Current Test	OK																						

Diagnostic Tests

Instrument Serial #: 80-001230

Location	Date	Time	Source
TYNDALL AFB	05/30/2007	07:47:14	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	06/10/2007	06:41:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	07/28/2007	07:06:17	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	08/13/2007	10:15:18	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-001230

Location	Date	Time	Source
TYNDALL AFB	08/13/2007	10:15:18	Local Diagnostic
		Test	Result
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	08/31/2007	09:29:44	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	09/30/2007	09:56:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	11/04/2007	08:44:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	12/28/2007	10:40:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001230

Location	Date	Time	Source
TYNDALL AFB	12/28/2007	10:40:06	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
TYNDALL AFB	12/28/2007	10:49:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001231

Location	Date	Time	Source
AUBURNDALE PD	08/19/2007	08:45:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
AUBURNDALE PD	08/19/2007	08:46:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001242

Location	Date	Time	Source
DAYTONA BEACH SHORES	03/16/2007	10:42:27	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
DAYTONA BEACH SHORES	05/19/2007	00:42:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001245

Location	Date	Time	Source
PORT ORANGE P.D.	06/27/2007	10:27:14	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001249

Location	Date	Time	Source
BROWARD CO SO	08/29/2007	12:12:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
BROWARD CO SO	10/10/2007	15:11:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	Fail
		Modem Test	OK
		Temperature Regulation Test	OK
BROWARD CO SO	10/10/2007	15:12:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	Fail
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001258

Location	Date	Time	Source
ORANGE COUNTY S.O.	06/13/2007	13:33:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ORANGE COUNTY S.O.	12/13/2007	08:10:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001259

Location	Date	Time	Source
PINELLAS COUNTY SO	03/09/2007	23:57:14	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
PINELLAS COUNTY SO	10/20/2007	21:34:15	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
PINELLAS COUNTY SO	11/28/2007	21:30:31	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
PINELLAS COUNTY SO	11/28/2007	21:31:11	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001259

Location	Date	Time	Source
PINELLAS COUNTY SO	11/28/2007	21:31:11	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	11/28/2007	21:31:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	12/12/2007	21:58:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	12/12/2007	22:05:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PINELLAS COUNTY SO	12/29/2007	02:23:31	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001259

Location	Date	Time	Source
PINELLAS COUNTY SO	12/29/2007	02:23:31	Local Diagnostic
	Test	Result	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001264

Location	Date	Time	Source
MELBOURNE BEACH PD	09/08/2007	17:45:02	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001265

Location	Date	Time	Source
PALM BAY PD	08/30/2007	18:29:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BAY PD	08/30/2007	18:31:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BAY PD	10/13/2007	19:43:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BAY PD	10/13/2007	19:45:28	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001265

Location	Date	Time	Source
PALM BAY PD	10/13/2007	19:45:28	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BAY PD	10/15/2007	14:44:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001269

Location	Date	Time	Source
PALM BEACH CO SO	05/04/2007	08:38:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
PALM BEACH CO SO	06/18/2007	11:56:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
PALM BEACH CO SO	06/18/2007	12:34:05	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001272

Location	Date	Time	Source
SEMINOLE S.O.	05/05/2007	21:48:22	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001276

Location	Date	Time	Source
MIAMI-DADE PD	11/03/2007	01:08:52	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001280

Location	Date	Time	Source
JACKSONVILLE SO	02/20/2007	11:09:47	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001282

Location	Date	Time	Source
U OF FLORIDA PD	04/02/2007	22:36:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
U OF FLORIDA PD	04/02/2007	22:46:39	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
U OF FLORIDA PD	04/02/2007	22:56:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
U OF FLORIDA PD	04/26/2007	08:25:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001282

Location	Date	Time	Source
U OF FLORIDA PD	04/26/2007	08:25:01	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
U OF FLORIDA PD	04/26/2007	08:38:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001283

Location	Date	Time	Source
HIGH SPRINGS PD	07/19/2007	08:14:52	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001284

Location	Date	Time	Source
GILCHRIST COUNTY SO	07/13/2007	05:30:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GILCHRIST COUNTY SO	07/13/2007	08:14:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GILCHRIST COUNTY SO	07/13/2007	08:15:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GILCHRIST COUNTY SO	09/12/2007	08:13:10	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001284

Location	Date	Time	Source
GILCHRIST COUNTY SO	09/12/2007	08:13:10	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GILCHRIST COUNTY SO	10/24/2007	07:19:55	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001285

Location	Date	Time	Source
GILCHRIST COUNTY SO	07/13/2007	07:08:51	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001288

Location	Date	Time	Source
UNION COUNTY SO	01/05/2007	11:13:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
UNION COUNTY SO	01/05/2007	11:24:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
UNION COUNTY SO	01/05/2007	11:25:23	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
UNION COUNTY SO	01/09/2007	10:45:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001288

Location	Date	Time	Source
UNION COUNTY SO	01/09/2007	10:45:21	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
UNION COUNTY SO	06/06/2007	01:16:09	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
UNION COUNTY SO	10/03/2007	11:42:53	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001289

Location	Date	Time	Source
UNION COUNTY SO	01/05/2007	10:58:52	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
UNION COUNTY SO	01/05/2007	11:00:03	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
UNION COUNTY SO	01/05/2007	11:20:42	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
UNION COUNTY SO	07/23/2007	13:02:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001289

Location	Date	Time	Source
UNION COUNTY SO	07/23/2007	13:02:01	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
UNION COUNTY SO	07/23/2007	13:04:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
UNION COUNTY SO	07/23/2007	13:08:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001292

Location	Date	Time	Source
LEVY COUNTY SO	04/30/2007	14:27:28	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-001293

Location	Date	Time	Source
WILLISTON PD	02/16/2007	00:43:25	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001302

Location	Date	Time	Source
SANTA ROSA COUNTY SO	01/06/2007	00:54:29	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA COUNTY SO	02/03/2007	01:51:39	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA COUNTY SO	03/10/2007	01:58:41	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA COUNTY SO	04/07/2007	01:42:47	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001302

Location	Date	Time	Source
SANTA ROSA COUNTY SO	04/07/2007	01:42:47	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	05/05/2007	02:38:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	06/02/2007	01:17:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	07/06/2007	23:50:32	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	08/11/2007	03:06:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001302

Location	Date	Time	Source
SANTA ROSA COUNTY SO	08/11/2007	03:06:00	Local Diagnostic
		Test	Result
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
SANTA ROSA COUNTY SO	08/11/2007	03:06:32	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
SANTA ROSA COUNTY SO	08/11/2007	03:14:11	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	09/15/2007	01:36:29	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK

Diagnostic Tests

Instrument Serial #: 80-001302

Location	Date	Time	Source
SANTA ROSA COUNTY SO	09/15/2007	01:36:29	Local Diagnostic
		Test	Result
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	10/22/2007	13:52:09	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	11/03/2007	01:18:14	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	12/08/2007	14:00:15	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001303

Location	Date	Time	Source
SANTA ROSA SO	09/14/2007	23:58:55	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA SO	09/15/2007	00:35:33	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA SO	09/15/2007	00:37:31	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SANTA ROSA SO	10/22/2007	11:30:00	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001303

Location	Date	Time	Source
SANTA ROSA SO	10/22/2007	11:30:00	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA SO	11/02/2007	23:02:40	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SANTA ROSA COUNTY SO	12/08/2007	11:40:06	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001305

Location	Date	Time	Source
MARIANNA PD	06/25/2007	02:00:05	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			Fail

Diagnostic Tests

Instrument Serial #: 80-001306

Location	Date	Time	Source
OKALOOSA SO	06/12/2007	15:22:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
OKALOOSA SO	12/05/2007	13:33:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001308

Location	Date	Time	Source
BAY COUNTY SO	03/11/2007	17:49:16	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001311

Location	Date	Time	Source
WALTON COUNTY SO	05/11/2007	11:09:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
WALTON COUNTY SO	06/15/2007	08:09:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001312

Location	Date	Time	Source
WALTON COUNTY SO	05/03/2007	12:21:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
WALTON COUNTY SO	05/03/2007	12:22:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
WALTON COUNTY SO	06/15/2007	08:05:24	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
WALTON COUNTY SO	06/15/2007	08:09:15	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001312

Location	Date	Time	Source
WALTON COUNTY SO	06/15/2007	08:09:15	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001313

Location	Date	Time	Source
SPRINGFIELD PD	04/17/2007	13:05:45	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SPRINGFIELD PD	04/18/2007	11:58:33	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SPRINGFIELD PD	04/22/2007	13:17:38	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001328

Location	Date	Time	Source
INDIAN RIVER CO SO	07/13/2007	11:52:44	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001344

Location	Date	Time	Source
SARASOTA COUNTY SO	03/23/2007	08:20:34	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SARASOTA COUNTY SO	03/24/2007	20:33:46	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SARASOTA COUNTY SO	05/10/2007	11:53:26	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	Fail	
	Temperature Regulation Test	OK	
SARASOTA COUNTY SO	05/10/2007	11:55:19	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001344

Location	Date	Time	Source
SARASOTA COUNTY SO	05/10/2007	11:55:19	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
SARASOTA COUNTY SO	09/17/2007	11:06:05	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001345

Location	Date	Time	Source
EUSTIS P.D.	07/15/2007	12:23:06	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-001350

Location	Date	Time	Source
FRUITLAND PARK P.D.	09/10/2007	09:38:21	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
FRUITLAND PARK P.D.	09/10/2007	09:51:56	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001360

Location	Date	Time	Source
EVERGLADES NAT PARK	07/19/2007	13:13:45	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	Fail
		Temperature Regulation Test	OK
EVERGLADES NAT PARK	07/19/2007	13:59:41	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001364

Location	Date	Time	Source
GAINESVILLE PD	03/07/2007	10:32:49	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
GAINESVILLE PD	03/18/2007	23:57:22	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
GAINESVILLE PD	05/02/2007	09:20:23	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
GAINESVILLE PD	05/02/2007	10:27:29	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001364

Location	Date	Time	Source
GAINESVILLE PD	05/02/2007	10:27:29	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
GAINESVILLE PD	11/01/2007	10:14:15	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001365

Location	Date	Time	Source
LEVY COUNTY SO	05/31/2007	09:00:29	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001442

Location	Date	Time	Source
BISCAYNE NAT. PARK	11/12/2007	12:14:08	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001443

Location	Date	Time	Source
CLAY COUNTY SO	03/24/2007	12:00:01	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLAY COUNTY SO	09/14/2007	10:04:02	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001469

Location	Date	Time	Source
HURLBURT FIELD PD	06/15/2007	15:46:35	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001471

Location	Date	Time	Source
PATRICK A.F.B.	06/29/2007	02:09:45	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001646

Location	Date	Time	Source
BAY COUNTY SO	03/11/2007	17:58:44	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001647

Location	Date	Time	Source
CAPE CORAL PD	12/05/2007	15:20:03	Remote Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-001653

Location	Date	Time	Source
ST PETERSBURG PD	09/07/2007	12:10:36	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST PETERSBURG PD	09/10/2007	09:10:14	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST PETERSBURG PD	09/10/2007	14:33:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001655

Location	Date	Time	Source
ST. JOHNS CO SO	05/07/2007	03:05:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
ST. JOHNS CO SO	06/30/2007	13:00:31	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001657

Location	Date	Time	Source
MICCOSUKEE PD	11/12/2007	11:11:25	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MICCOSUKEE PD	11/12/2007	11:12:43	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
MICCOSUKEE PD	11/27/2007	11:36:25	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001731

Location	Date	Time	Source
HILLSBOROUGH SO	01/20/2007	23:46:34	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	03/16/2007	22:26:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HILLSBOROUGH SO	07/19/2007	09:58:58	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-001737

Location	Date	Time	Source
SOUTH MIAMI P.D.	10/09/2007	23:05:50	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-001740

Location	Date	Time	Source
CLEARWATER PD	10/23/2007	15:27:53	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLEARWATER PD	10/29/2007	13:59:47	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLEARWATER PD	10/29/2007	15:55:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLEARWATER PD	10/31/2007	08:43:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-001740

Location	Date	Time	Source
CLEARWATER PD	10/31/2007	08:43:19	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLEARWATER PD	11/01/2007	08:20:30	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLEARWATER PD	11/01/2007	10:33:12	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLEARWATER PD	11/07/2007	14:07:16	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
CLEARWATER PD	11/07/2007	14:58:19	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK

Diagnostic Tests

Instrument Serial #: 80-001740

Location	Date	Time	Source
CLEARWATER PD	11/07/2007	14:58:19	Local Diagnostic
	Test	Result	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	

Diagnostic Tests

Instrument Serial #: 80-002170

Location	Date	Time	Source
NAS KEY WEST	02/23/2007	12:51:10	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-002231

Location	Date	Time	Source
NEW SYMRNA BEACH PD	09/21/2007	01:04:34	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
NEW SYMRNA BEACH PD	09/30/2007	18:48:55	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	OK	
NEW SYMRNA BEACH PD	12/30/2007	19:58:40	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	
NEW SYMRNA BEACH PD	12/30/2007	20:00:55	Local Diagnostic
	Test	Result	
	Voltage/Current Test	OK	
	RAM Test	OK	
	EEPROM Checksum Test	OK	
	Real Time Clock Test	OK	
	DSP Test	OK	
	Analytical Stability Test	OK	

Diagnostic Tests

Instrument Serial #: 80-002231

Location	Date	Time	Source
NEW SYMRNA BEACH PD	12/30/2007	20:00:55	Local Diagnostic
	Test	Result	
	Internal Printer Test	OK	
	Modem Test	OK	
	Temperature Regulation Test	Fail	

Diagnostic Tests

Instrument Serial #: 80-002232

Location	Date	Time	Source
MIAMI BEACH PD	01/07/2007	23:59:22	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
MIAMI BEACH PD	10/25/2007	11:22:32	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK

Diagnostic Tests

Instrument Serial #: 80-002462

Location	Date	Time	Source
HIALEAH P. D.	12/11/2007	15:03:02	Local Diagnostic
Test			Result
Voltage/Current Test			OK
RAM Test			OK
EEPROM Checksum Test			OK
Real Time Clock Test			OK
DSP Test			OK
Analytical Stability Test			OK
Internal Printer Test			OK
Modem Test			OK
Temperature Regulation Test			Fail

Diagnostic Tests

Instrument Serial #: 80-002463

Location	Date	Time	Source
HIALEAH P.D.	07/30/2007	14:46:58	Local Diagnostic
Test	Result		
Voltage/Current Test	OK		
RAM Test	OK		
EEPROM Checksum Test	OK		
Real Time Clock Test	OK		
DSP Test	OK		
Analytical Stability Test	OK		
Internal Printer Test	OK		
Modem Test	OK		
Temperature Regulation Test	OK		

Diagnostic Tests

Instrument Serial #: 80-002464

Location	Date	Time	Source
HIALEAH P.D.	08/02/2007	11:04:48	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
HIALEAH P.D.	08/28/2007	14:39:54	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
HIALEAH P.D.	08/29/2007	09:37:04	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail

Diagnostic Tests

Instrument Serial #: 80-002566

Location	Date	Time	Source
SURFSIDE P.D.	08/09/2007	15:58:25	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
SURFSIDE P.D.	08/09/2007	16:06:57	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	Fail
SURFSIDE P.D.	08/09/2007	16:22:59	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SURFSIDE P.D.	08/23/2007	16:36:00	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK

Diagnostic Tests

Instrument Serial #: 80-002566

Location	Date	Time	Source
SURFSIDE P.D.	08/23/2007	16:36:00	Local Diagnostic
		Test	Result
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK
SURFSIDE P.D.	09/01/2007	15:34:20	Local Diagnostic
		Test	Result
		Voltage/Current Test	OK
		RAM Test	OK
		EEPROM Checksum Test	OK
		Real Time Clock Test	OK
		DSP Test	OK
		Analytical Stability Test	OK
		Internal Printer Test	OK
		Modem Test	OK
		Temperature Regulation Test	OK